



IC 1	74LS00	IC 11	74LS14	IC 21	8226P	IC 31	74LS241	IC 41	74LS14	IC 51	8226P	IC 61	74LS241	IC 71	74LS14	IC 81	74LS14	IC 91	74LS14
2	74LS04	12	74LS14	22	8226P	32	74LS241	42	74LS14	52	8226P	62	74LS241	72	74LS14	82	74LS14	92	74LS14
3	74LS14	13	74LS05	23	74LS273	33	74LS04	43	74LS14	53	74LS273	63	74LS04	73	74LS14	83	74LS14	93	74LS14
4	74LS14	14	74LS155	24	74LS273	34	74LS04	44	74LS14	54	74LS273	64	74LS04	74	74LS14	84	74LS14	94	74LS14
5	74LS05	15		25	74LS02	35	74LS04	45	74LS14	55		65	74LS04	75	74LS14	85	74LS14	95	74LS14
6		16		26		36		46		56		66		76		86		96	
7		17		27		37		47		57		67		77		87		97	
8		18		28		38		48		58		68		78		88		98	
9		19		29		39		49		59		69		79		89		99	
10		20		30		40		50		60		70		80		90		100	

02	03	Unterlagenstand	TASA	Blattzahl
64234		4.8.82	Inkermann	1
63160		23.10.81		1
206909000002		A041		
HELL		Ersatz für Zeichnung gl. Nr. v. 13.V.81		